



State of Utah  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt  
Governor

Ted Stewart  
Executive Director

James W. Carter  
Division Director


355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340  
801-359-3940 (Fax)  
801-538-5319 (TDD)

M/003/004

0001

September 6, 1995

TO: Minerals File

FROM: Lynn Kunzler, Reclamation Specialist 

RE: Site Inspection, Interstate Brick Company, Montello Mine, M/003/004, Box Elder County, Utah

Date of Inspection: August 31, 1995  
Time of Inspection: 3:00 p.m.  
Conditions: Sunny and warm  
Participants: Tom Munson, and Lynn Kunzler, DOGM

Apparently there has been no change at this site from the 1991 inspection, and possibly from the 1986 inspection. There is a large stockpile of clay at this site. The lower site is approximately three acres in size; most of which appears to have been regraded, although they have not pushed the topsoil back over this site.

The larger site is about 13 acres in size and apparently no regrading has been done there. The two pits are separated by approximately one mile of road. The first 3/10ths of a mile of road coming from the large pit is doubled on the other side of the drainage so it kind of makes a loop. This site is bonded for \$286,000 with a Board Contract.

At the lower pit there was quite a bit of vegetation growing along the access road going into the pit, including russian wildrye, crested wheatgrass, indian ricegrass, bluebunch wheatgrass, fourwing saltbrush, rabbitbrush and foxtail.

jb  
M003004.ins



0001